

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 06/15/2023	APWS Task ID: A561715E0234426B998FFCE714545EC	APWS Project ID: 2E977A60162C43909832A7402E6C3274
Procedure: ILS OR LOC RWY 5 AMDT 38B		Enroute: NO	Specialist: Teffeteller, David		Agreement Number:
Airport ID: KCLT			Airport City: CHARLOTTE		State: NC
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: RWY 05/23 PERM CLOSED CONTACT DAVE TEFFETELLER/240-457-1998 QUALITY 45 CHECKED					

LOC I-CLT <u>110.95</u>	APP CRS 055°	Rwy Idg 7092 TDZE 716 Apt Elev 748
-----------------------------------	------------------------	---


ILS or LOC RWY 5
CHARLOTTE/DOUGLAS INTL (CLT)

T Circling NA at night.
RADAR required.
* RVR 1800 authorized with use of FD or AP or HUD to DA.



MISSED APPROACH: Climb to 4000 via heading 055° and CLT VOR/DME R-050 to ATELL INT/CLT 12.1 DME and hold, continue climb-in-hold to 4000.

D-ATIS	CHARLOTTE APP CON		CHARLOTTE TOWER		GND CON		CLNC DEL
ARR 121.15	(001°-119°) 128.32	(Rwys 18L-36R, 5-23) 118.1	257.8		121.8	348.6 (WEST)	127.15
DEP 132.1	(120°-295°) 120.05	(Rwy 18C-36C) 126.4	257.8		121.9	348.6 (EAST)	348.6
	(296°-360°) 134.75	(Rwy 18R-36L) 133.35	257.8				
	(180°-359°) 257.2	110.8 BZM Chan 45					CPDLC
	(360°-179°) 307.8						



VGSI and ILS glidepath not coincident
(VGSI Angle 3.00/TCH 89).

