FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE TRANSMITTAL OF AIRWAYS/ROUTES DATA RECORD

AIRWAY NO or ROUTE Q232

ROUTINE or DOCKET NO

23-AEA-10

<u>FROM</u> STUBN			<u>STA</u> N		TO CORDS				STATE PA	FB/FO FB	<u>RNP</u> 2.00	LEG TYPE TF
OBSTRUCTION			COORDINATES			ELEV MSL	CONT OBS	<u>AC</u>	<u>R0(</u>	<u>C ADJL</u>	<u>JSTMENTS</u>	
MRA	MOCA	PUB	<u>MAA</u> 45000	<u>D/D/I</u> 18000	<u>MEA (1)</u>	DIRECTION (<u>1)</u>	<u>MEA (2)</u>	DIRECTIC) <u>N (2)</u>		<u>SS MEA</u> 8000
COP		<u>FIX N</u>		<u>RA</u>	FIX MCA			MTA				
<u>SEGMENT REMARKS</u> NEW SEGMENT. REQUIRED DME FACILITIES: JFK, JHW, BUF, HNK, ETG, HUO, SLT, SAX, RBV, PSB, SYR <u>CHANGES-REASONS</u>												
<u>FROM</u> CORDS			<u>ST/</u> P		TO NEION				<u>STATE</u> NJ	FB/FO FB	<u>RNP</u> 2.00	LEG TYPE TF
OBSTRUCTION			<u>COORDINATES</u>			ELEV MSL	CONT OBS	<u>AC</u>	<u>R0(</u>	<u>C ADJU</u>	<u>JSTMENTS</u>	
<u>MRA</u>	MOCA	PUB	MAA 45000	<u>D/D/I</u> 18000	<u>MEA (1)</u>	<u>DIRECTION (</u>	<u>1)</u>	<u>MEA (2)</u>	DIRECTIC	<u>DN (2)</u>		<u>SS MEA</u> 8000
COP				<u>FIX M</u>	<u>RA</u>	<u>FIX M</u>	CA			<u>MTA</u>	<u>L</u>	

SEGMENT REMARKS

NEW SEGMENT.

REQUIRED DME FACILITIES: RBV, HNK, CYN, HUO, JFK, SAX, CCC

CHANGES-REASONS

0^{1)AL}/7₂ 18 CHECKER

FEDERAL AVIATION ADMINISTRATION FLIGHT STANDARDS SERVICE TRANSMITTAL OF AIRWAYS/ROUTES DATA RECORD

AIRWAY NO or ROUTE

ROUTINE or DOCKET NO 23-AEA-10										
FLIGHT CHECK				CHANGES REOLURIN		Jan 03, 2024				
PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.										
APPROVED	<u>DATE</u> 05/16/2024	<u>OFFICE</u> AJV-A423	<u>TITLE</u> MANAGER	Digitally signed by ALLAN WILL	<u>name</u> Michael R. G	GARRITY JR.				
				Jan 03, 2024						

