

RNAV (GPS) RWY 32

EASTPORT MUNI (EPM)

MISSED APPROACH:
Climb to 4000 direct
PIERR and hold,
continue climb-in-hold
to 4000.

UNICOM
122.8 (CTAF) **L**

MSA RW32 25 NM

2200

PROTOTYPE-
NOT FOR NAVIGATION

4000
↑
PIERR
RW32
VGSi and RNAV glidepath not coincident (VGSi Angle 3.28/TCH 44)
JEXAT 2 NM to RW32
FEGUD 1600
LUBCI
4 NM Holding Pattern
1600
323° (307°T)
143° (127°T)
7000
3000
GP 3.28°
TCH 55°

--	--

MIRL Rwy 14-32 **L**
REIL Rwy 14 and 32 **L**