

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 02/20/2025	APWS Task ID: C45B58C95DE94585AC70F400AB28A978	APWS Project ID: 39F528B5B4BE4EC8987AE54BE9CC9794
Procedure: LOC RWY 28L AMDT 3E		Enroute: NO	Specialist: Wilkinson, Christopher		Agreement Number:
Airport ID: KHW			Airport City: HAYWARD		State: CA
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: ACTIVE AND PENDING AIRNAV DATA USED FOR KHW AND RWY 28L. CLEAR NOTAM FDC 3/0501. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION CONTACT: JOSEPH ZEDER, (405) 954-9111. QUALITY 38 CHECKED QUALITY 34 CHECKED					

LOC/DME RWY 28L
HAYWARD EXEC (HWD)

MISSED APPROACH: Climb to 2100
direct OAK VOR/DME and hold.

OAKLAND
116.8 OAK
Chan 115

LOCALIZER 111.5
I-HWD
Chan 52
LOC offset 3.00°

R-300 120°
300°

947△
318±△
70±△
237△
179△
831±△
1575±△
978△
1805△
2328△
1289.

RISHE
I-HWD [4.8]
FERNE
I-HWD [7.4]

JIBAN INT
I-HWD [12.7]

(IF)
BRIEN INT
I-HWD [15.4]

3024•
3817•
2962•
3951•

113.9 OSI Chan 86
R-046
R-052
3049△
3700
288°
(2.7)

113.9 OSI Chan 86
R-009
108°

ELEV 52 TDZE 50

Procedure NA for arrivals at SJC VOR/DME on V334 and T259.

IAF SAN JOSE
114.1 SJC
Chan 88

MSA OAK 25 NM
3800
5100
170°
350°

MIRL Rwy 10R-28L
MIRL Rwy 10L-28R
REIL Rwy 10R and 28L

SW-2, 08 AUG 2024 to 05 SEP 2024