

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 05/16/2024	APWS Task ID: C7F73E21E0AD4425B2825596AAEBA7F0	APWS Project ID: A100817577004611858546248C3A5E0B
Procedure: ILS OR LOC RWY 4 AMDT 8B		Enroute: NO	Specialist: Boone-walt, Rose		Agreement Number:
Airport ID: KMZZ			Airport City: MARION		State: IN
Facility ID: MZZ	Facility Type: ILS	Flight Inspection Remark Type:			
Procedure Comments: CLEARs NOTAM 3/2920 Processed IAW Technical Support Group (AJF-17) Memo dated 07/07/2021, Subject: Guidance for Procedural Changes Requiring Flight Inspection/Validation CONTACT: DAVID M. DANNER AJV-A421 LEAD: 405.954.5077 QUALITY 41 CHECKED QUALITY 32 CHECKED Digitally signed by PABLO ORTIZ-JR Feb 21, 2024					


LOC I-MZZ 111.7	APP CRS 041°	Rwy Idg TDZE Apt Elev	6011 858 859
---------------------------	------------------------	-----------------------------	---

OLD


ILS or LOC RWY 4

MARION MUNI - MCKINNEY FLD (MZZ)

DME required. ▼ DME from MZZ VOR/DME. Simultaneous reception of I-MZZ and MZZ DME required. For inop ALS, increase S-LOC 4 Cats C and D visibility to 1½ SM. ▲ NA		MALSR ⬆️	MISSED APPROACH: Climb to 2500 then climbing left turn to 4000 on heading 320° to intercept GUS VORTAC R-090 to AGACI/ GUS VORTAC 16 DME/RADAR and hold.
AWOS-3 108.6	GRISSOM APP CON ★ 121.05 338.275	CLNC DEL 120.0	UNICOM 122.7 (CTAF) 0



Remain within 10 NM		AKICA MZZ 13.3	JOSKO MZZ 7.3	2500 ↑	4000 ↖ hdg 320°	GUS R-090	AGACI GUS 16 RADAR
3000 GS 3.00° TCH 52		221°	3000	CIVIL MZZ 3.7	MZZ 1.8	MZZ 0.7	
041°		041°	3000	1860			
		6 NM	3.6 NM	1.9 NM	1.1 NM		
CATEGORY	A	B	C	D			
S-ILS 4	1058-½		200 (200-½)				
S-LOC 4	1260-½	402 (500-½)	1260-¾	402 (500-¾)			
CIRCLING	1300-1 441 (500-1)	1320-1 461 (500-1)	1420-1½ 561 (600-1½)	1500-2 641 (700-2)			



ILS or LOC RWY 4