

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: CE670A60C271479BA82450CBF938C3FB	APWS Project ID: 6D15FDABDC644E9DA3F26392258DE51F
Procedure: RNAV (GPS) RWY 36 ORIG-E		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: M17			Airport City: BOLIVAR		State: MO
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums. PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. CONTACT: CASEY HILL (405) 954-0624. QUALITY 6 SN 4/23/26 CHECKED QUALITY 41 CHECKED					

WAAS CH 78303 W36A	APP CRS 359°	Rwy Ldg TDZE 1092 Apt Elev 1092
--	------------------------	---

RNAV (GPS) RWY 36
BOLIVAR MUNI (M17)

RNP APCH - GPS. ▼ Rwy 36 helicopter visibility reduction below ¾ SM NA. ▲ NA Use Springfield-Branson Ntl altimeter setting. Circling Rwy 18 NA at night.	MISSED APPROACH: Climb to 3000 direct OSOYE and hold.
---	---

SPRINGFIELD APP CON 124.95 318.2	UNICOM 123.0 (CTAF) 0
--	---------------------------------

