

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 03/25/2021	APWS Task ID: D1CDA3A1F9FE4BE09651983F05D70F23	APWS Project ID: 9BBF0DC2B68E446AB0CC8635EADA58F0
Procedure: RNAV (GPS) RWY 9 AMDT 0C		Enroute: NO	Specialist: Lafferty, James		Agreement Number:
Airport ID: 14G	Airport Name: FREMONT		Airport City: FREMONT		State: OH
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: P-NOTAM This Cancels FDC 0/1070 and FDC 9/6474 Order 8260.3, chapter 2, New Circling Criteria Applied Contact Dave Teffeteller at 202-267-5177					



APP CRS	Rwy Idg	4011
095°	TDZE	663
	Apt Elev	663

RNAV (GPS) RWY 9
FREMONT (14G)

RNP APCH.	Procedure NA at night. Use Sandusky County Rgnl altimeter setting; when not received use Toledo Executive altimeter setting and increase all MDA 40 feet and LNAV Cat D and Circling Cat C visibility ¼ mile. Rwy 9 helicopter visibility reduction below 1 SM NA.	MISSED APPROACH: Climbing right turn to 2600 direct KADBY and hold.
-----------	--	--

TOLEDO APP CON 126.1 307.0	UNICOM 122.8 (CTAF) 0
-------------------------------	--------------------------



