NAME: COYAN STATE: OH **COUNTRY: US ICAO REGION CODE: K5**

LATITUDE/LONGITUDE: 395257.84N/0825005.26W TYPE: WP

AIRSPACE DOCKET: FIX TYPE OF ACTION: MODIFY

HOLDING: **HOLDING TYPE OF ACTION: NO CHANGE**

FIX USE:

CITY COLUMBUS **USE TITLE** RNAV (GPS) RWY 23L USE TYPE AIRPORT IDENT FAC PAT **STATE** KLCK OH (US)

REQUIRED CHARTING: MILITARY IAP, IAP

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 1 DATE OF REVISION: 05/16/2024

REASON FOR REVISION:

1. REMOVED "RNP CRITERIA APPLIED." REMARK. 2. REMOVED FIX MAKE-UP FACILITIES.

3. ADDED FIX USE "RNAV (GPS) RWY 23L"

INITIATED BY: DATE: **ORGANIZATION:** NAME:

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A421 **NAME: WALKER MILLIGAN**

APPROVED BY: DATE: 05/16/2024 OFFICE: AJV-A421 **NAME: DAVID DANNER**

SIGNATURE:

Digitally signed by **DAVID DANNER** Mar 29, 2024

FAA FORM 8260-2 / FEB 2012 Page 1 of 1

NAME: TIYOY STATE: OH **COUNTRY: US ICAO REGION CODE: K5**

LATITUDE/LONGITUDE: 400125.76N/0824957.10W TYPE: WP. DME

AIRSPACE DOCKET: FIX TYPE OF ACTION: MODIFY

FIX MAKE-UP FACILITIES:

FAC NAME **IDENT TYPE CLASS MAG** TRUE DME DIST FROM FAC MRA MAA BRG **BRG** NM FEET **APPLETON** APE **VORTAC** VΗ 241.93 235.93 13.59 3000 17500

HOLDING: HOLDING TYPE OF ACTION: NO CHANGE

FIX USE:

USE TYPE USE TITLE FAC PAT AIRPORT IDENT CITY **STATE EN ROUTE** (US) RNAV (GPS) RWY 23L OH (US) **KLCK COLUMBUS**

REQUIRED CHARTING: MILITARY IAP, IAP, EN ROUTE LOW, CONTROLLER LOW

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 1 DATE OF REVISION: 05/16/2024

REASON FOR REVISION:

1. FIX MAKE-UP FACILITIES: APE VORTAC CLASS UPDATED FROM "H" TO "VH."
2. FIX MAKE-UP: REMOVED FAC 2 "ZAVTA."
3. FIX USE: CORRECTED FIX USE FORMAT FOR "IAP RNAV (GPS) RWY 23L KLCK" AND "EN ROUTE V5 FAC 1."
4. CHARTING: UPDATED "CONTROLLER" TO "CONTROLLER LOW"

INITIATED BY: DATE: **ORGANIZATION:** NAME:

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A421 **NAME: DALLIN STRICKLAND**

APPROVED BY: DATE: 05/16/2024 OFFICE: AJV-A421 NAME: DAVID DANNER

> SIGNATURE: Digitally signed by

DAVID DANNER Mar 29, 2024

FAA FORM 8260-2 / FEB 2012 Page 1 of 1

NAME: UCECU STATE: OH **COUNTRY: US ICAO REGION CODE: K5**

LATITUDE/LONGITUDE: 395337.56N/0823957.64W TYPE: WP

AIRSPACE DOCKET: FIX TYPE OF ACTION: MODIFY

HOLDING: **HOLDING TYPE OF ACTION: NO CHANGE**

FIX USE:

CITY COLUMBUS **USE TITLE** RNAV (GPS) RWY 23L USE TYPE IAP AIRPORT IDENT FAC PAT **STATE** KLCK OH (US)

REQUIRED CHARTING: MILITARY IAP, IAP

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 1 DATE OF REVISION: 05/16/2024

REASON FOR REVISION:

1. REMOVED FIX MAKE-UP FACILITIES. 2. ADDED FIX USE TYPE "RNAV (GPS) RWY 23L"

INITIATED BY: DATE: **ORGANIZATION:** NAME:

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A421 NAME: WALKER MILLIGAN

APPROVED BY: **DATE:** 05/16/2024 OFFICE: AJV-A421 **NAME: DAVID DANNER**

> Digitally signed by SIGNATURE:

> > **DAVID DANNER** Mar 29, 2024



FAA FORM 8260-2 / FEB 2012 Page 1 of 1

NAME: VUTUY STATE: OH COUNTRY: US ICAO REGION CODE: K5

LATITUDE/LONGITUDE: 395035.50N/0825312.26W **TYPE**: WP

AIRSPACE DOCKET: FIX TYPE OF ACTION: MODIFY

HOLDING: HOLDING TYPE OF ACTION: NO CHANGE

FIX USE:

USE TYPE USE TITLE FAC PAT AIRPORT IDENT CITY STATE
IAP RNAV (GPS) RWY 23L KLCK COLUMBUS OH (US)

REQUIRED CHARTING: MILITARY IAP, IAP

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 1 DATE OF REVISION: 05/16/2024

REASON FOR REVISION:

1. REMOVED FIX MAKE-UP "KLCK R23L" - WP ONLY

INITIATED BY: DATE: ORGANIZATION: NAME:

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A421 NAME: WALKER MILLIGAN

APPROVED BY: DATE: 05/16/2024 OFFICE: AJV-A421 NAME: DAVID DANNER

SIGNATURE: Digitally signed by

DAVID DANNER Mar 29, 2024

> ONALITY 21 CHECKED

FAA FORM 8260-2 / FEB 2012 Page 1 of 1

NAME: ZAVTA STATE: OH COUNTRY: US ICAO REGION CODE: K5

LATITUDE/LONGITUDE: 395711.53N/0824431.18W **TYPE**: WP

AIRSPACE DOCKET: FIX TYPE OF ACTION: MODIFY

HOLDING: HOLDING TYPE OF ACTION: MODIFY

PATTERNS:

LEG LENGTH HOLDING ALTITUDES TEMPLATES **IDENT TYPF** RAD/CRS/BRG **CRS** TURN PAT DIR (LORR) TIME DME INBOUND MAX MIN MAX MIN WP NE 052.43 3000 6000 232.43 6

CONTROLLING OBSTRUCTIONS:

PAT AIRSPEED OBSTRUCTION COORDINATES ELEVATION ACCURACY CODE

200 TOWER (39-001219) 400334.00N/0824213.00W 1549 5D

HOLDING RESTRICTIONS:

HOLDING LIMITED TO ESTABLISHED PATTERN

REMARKS:

PRECIPITOUS TERRAIN EVALUATION COMPLETED

FIX USE:

USE TYPEUSE TITLEFACPATAIRPORT IDENTCITYSTATEIAPRNAV (GPS) RWY 23L1KLCKCOLUMBUSOH (US)

REQUIRED CHARTING: MILITARY IAP, IAP

COMPULSORY REPORTING POINT: NO

RECORD REVISION NUMBER: 1 **DATE OF REVISION:** 05/16/2024

REASON FOR REVISION:

1. CHANGED CRS INBOUND FROM 230.43 TO 232.43 - MAGVAR CHANGE

2. REMOVED FIX MAKEUP FAC 1 - FIX IS WP ONLY.

INITIATED BY: DATE: ORGANIZATION: NAME:

OFFICE OF PRIMARY RESPONSIBILITY: AJV-A421 **NAME:** WALKER MILLIGAN

APPROVED BY: DATE: 05/16/2024 **OFFICE:** AJV-A421 **NAME:** DAVID DANNER

SIGNATURE: Digitally signed by

DAVID DANNER Mar 29, 2024

> ONALITY 21 CHECKER

FAA FORM 8260-2 / FEB 2012 Page 1 of 1