

Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 12/29/2022	APWS Task ID: DD204CA0902147E3911ECE338988C366	APWS Project ID: EDB4912671814FFDB6C33EBA12C79F98
Procedure: HI - VOR/DME OR TACAN RWY 15 AMDT 3		Enroute: NO	Specialist: Brooks, Charles		Agreement Number:
Airport ID: KBGR			Airport City: BANGOR		State: ME
Facility ID:	Facility Type:	Flight Inspection Remark Type:			

Procedure Comments:
PROCEDURE CANCELLATION.

CONTACT JASON KRETSCHMER, AJV-A421, 405-954-4019

Digitally signed by
JASON KRETSCHMER
Oct 19, 2022



BANGOR, MAINE

HI-VOR/DME or TACAN RWY 15

VORTAC BGR 114.8 Chan 95	APCH CRS 157°	Rwy Idg 11,440 TDZE 192 Arprt Elev 192
--	-------------------------	---

AL-39 [USAF]


BANGOR INTL (KBGR)

▼ * When ALS inop, increase CAT E vis to 1½ miles.
** Circling not authorized NE of Rwy 15-33.



MISSED APPROACH: Climb to 3000 via BGR VORTAC R-155 to BUDDI (R-155/15.7 DME) and hold.


ATIS 127.75	APP CON 118.925 239.3	TOWER 120.7 233.7	GND CON 121.9 348.6	ASR
-----------------------	---------------------------------	-----------------------------	-------------------------------	-----



NE-1, 11 AUG 2022 to 08 SEP 2022

NE-1, 11 AUG 2022 to 08 SEP 2022

EMERG SAFE ALT 100 NM 7500



ELEV 192	TDZE 192
157° 1.9 NM from VORTAC	
TDZL/CL Rwy 15 HIRL Rwy 15-33	
FAF to MAP 5.9 NM	
Knots	120 140 160 180 200
Min:Sec	2:57 2:32 2:13 1:58 1:46

BANGOR, MAINE
Amdt 3 14261

44°48'N-68°50'W

BANGOR INTL (KBGR)

HI-VOR/DME or TACAN RWY 15