

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 06/12/2025	APWS Task ID: E160930EEB8246639E569AD775D8E6D8	APWS Project ID: 49E47FA87B584AF7B34CAC9C44C7898B
Procedure: RNAV (GPS)-A ORIG		Enroute: NO	Specialist: Tyler, George		Agreement Number:
Airport ID: KDLC			Airport City: DILLON		State: SC
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: ACTIVE AIRNAV DATA UTILIZED FOR KDLC AND RWYS. VOR MON SUPPORTING FLO DECOMMISSIONING. CONTACT DAVID DANNER, AJV-A421, 405-954-5077. 04/18/25: THIS IS AN UPDATED COPY OF THE FORM DEVELOPED ON 11/20/24. 8260-3 1. ADDITIONAL FLIGHT DATA: DELETED "JEDBA TO RW7: 3.00/40." 2. ADDITIONAL FLIGHT DATA: ADDED "CHART PROFILE NOTE: VISUAL SEGMENT – OBSTACLES." QUALITY 35 CHECKED QUALITY 41 CHECKED					

APP CRS	Rwy Idg	N/A
070°	TDZE	N/A
	Apt Elev	133

RNAV (GPS)-A
DILLON COUNTY (DLC)

RNP APCH - GPS.		MISSED APPROACH: Climbing left turn to 3200 direct FIPRI and hold, continue climb-in-hold to 3200.
Rwy 7, 25 helicopter visibility reduction below 1 SM NA. Procedure NA at night. Use FLO altimeter setting; when not received, procedure NA.		
FLO ASOS-3 123.625	FLORENCE APP CON ★ 118.6 341.7	CTAF 122.9









