

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 10/29/2026	APWS Task ID: E19D10EB08D14B9F851DE1073D2AC2E9	APWS Project ID: CE876E1550BD46F5924DD9E430A8E7DC
Procedure: RNAV (GPS) RWY 11 AMDT 2A		Enroute: NO	Specialist: Secaida, Roni		Agreement Number:
Airport ID: KCAE			Airport City: COLUMBIA		State: SC
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: REASON FOR PROJECT: T-NOTAM CLEARING THIS CANCELS FDC 5/6333 Contact Casey Hill, (405) 954-0624 QUALITY 23 CHECKED QUALITY 39 CHECKED					

WAAS CH 61014 W11A	APP CRS 112°	Rwy Ldg TDZE 236 Apt Elev 236	8601
--	------------------------	---	-------------

RNAV (GPS) RWY 11
COLUMBIA METRO (CAE)

RNP APCH-GPS. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -6°C or above 54°C.	ALSIF-2 	MISSED APPROACH: Climb to 2500 direct CABKO and hold.
---	-------------	--

ATIS 120.15	COLUMBIA APP CON 124.15 338.2 (110°-289°) 133.4 285.6 (290°-109°)	COLUMBIA TOWER 119.5 257.8	GND CON 121.9 348.6
-----------------------	---	--------------------------------------	-------------------------------

