

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 12/26/2024	APWS Task ID: E384F059A2954896985C69B2F600A019	APWS Project ID: 39864438CBCF4CDD8C29D13BD39E6A15
Procedure: LOC RWY 6 AMDT 3E		Enroute: NO	Specialist: Hilley, Dustin		Agreement Number:
Airport ID: KGUP			Airport City: GALLUP		State: NM
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION DO NOT ISSUE UNTIL 10/31/2024 CONTACT JOHN BORDY 405-954-0980 QUALITY 9 CHECKED BEGUE QUALITY 30 CHECKED					

LOC/DME I-GUP 111.7 Chan 54	APP CRS 062°	Rwy Idg TDZE Apt Elev	7315 6465 6472
---	------------------------	-----------------------------	---

OLD

LOC RWY 6
GALLUP MUNI (GUP)

T

A NA Rwy 6 helicopter visibility reduction below $\frac{3}{4}$ SM NA.

MISSED APPROACH: Climb to 7500 then climbing right turn to 9000 direct GUP VORTAC and hold.

ASOS 118.375	ALBUQUERQUE CENTER 124.325 288.25	UNICOM 122.95 (CTAF) 0
------------------------	---	----------------------------------

