



Flight Procedures Cover Page	Task Action: Cancellation	Task Type: IAP	Estimated Chart Date: 05/14/2026	APWS Task ID: E67A6F4B450D41DEB3A842D7A9B46E72	APWS Project ID: A5E965048F9B4D5188364FC44E2FBBD8
Procedure: VOR RWY 6 AMDT 9B		Enroute: NO	Specialist: Bruno, John		Agreement Number:
Airport ID: 16G			Airport City: TIFFIN		State: OH
Facility ID: FBC	Facility Type: VORTAC	Flight Inspection Remark Type:			
Procedure Comments: Contact Casimir Tabaka 405-202-7857					

VORTAC FBC 108.2 Chan 19	APP CRS 073°	Rwy Idg TDZE 786 Apt Elev 786
--	------------------------	---


VOR RWY 6

SENECA COUNTY (16G)

DME required.		MISSED APPROACH: Climb to 2400 then left turn on FBC VORTAC R-073 to REBUT/FBC 21 DME and hold.	
AWOS-3 127.175	FDY ASOS 132.85	TOLEDO APP CON 120.8 317.55	UNICOM 123.0 (CTAF) 0



CATEGORY	A	B	C	D
S-6	1400-1	614 (700-1)	1400-1 $\frac{3}{4}$ 614 (700-1 $\frac{3}{4}$)	NA
CIRCLING	1400-1 614 (700-1)	1400-1 $\frac{1}{4}$ 614 (700-1 $\frac{1}{4}$)	1400-1 $\frac{3}{4}$ 614 (700-1 $\frac{3}{4}$)	NA



EC-2, 02 OCT 2025 to 30 OCT 2025

EC-2, 02 OCT 2025 to 30 OCT 2025