

Flight Procedures Cover Page	Task Action: Amendment	Task Type: IAP	Estimated Chart Date: 03/26/2020	APWS Task ID: E99E4369AC18420DBA3AA03771437723	APWS Request ID: B856F18FC2784FF6B862E69D01FD38CF
Procedure: VOR OR TACAN RWY 26 AMDT 20A		Enroute: NO	Specialist: Blanco, Joseph		Agreement Number:
Airport ID: TJSJ	Airport Name: LUIS MUNOZ MARIN INTL	Airport City: SAN JUAN			State:
Facility ID: SJU	Facility Type: VORTAC	Flight Inspection Remark Type:			

Procedure Comments:
ABBREVIATED AMENDMENT

PROCESSED IAW AIRCRAFT OPERATIONS GROUP (AJW-33) MEMO, OCTOBER 3, 2018, SUBJECT: FLIGHT INSPECTION REVIEW NOT REQUIRED

CONTACT ALLAN WILL, AJV-A423, 405-954-6103.



VORTAC SJU 114.0 Chan 87	APP CRS 249°	Rwy Idg TDZE Apt Elev	9600 7 9
---------------------------------------	------------------------	-----------------------------	-------------------------------------


OLD

VOR or TACAN RWY 26
LUIS MUNOZ MARIN INTL (SJU)(TJSJ)




⚠ Visibility reduction by helicopters NA. MISSED APPROACH: Climb to 2000 then climbing right turn to 3000 via heading 045° and SJU VORTAC R-004 to DEEDY INT/SJU 15 DME and hold.

D-ATIS 125.8	SAN JUAN APP CON 119.4 269.2 120.9 290.2 (WEST & SW) (NORTH & EAST)	SAN JUAN TOWER 132.05 257.8	GND CON 121.9 348.6	CLNC DEL 126.4 284.6	CPDLC
------------------------	---	---------------------------------------	-------------------------------	--------------------------------	-------

DME or RADAR REQUIRED




ELEV 9	D	TDZE 7
--------	----------	--------




CATEGORY	A	B	C	D	E
S-26	440-1	433 (500-1)	440-1¼ 433 (500-1¼)	440-1½	433 (500-1½)
CIRCLING	600-1	591 (600-1)	600-1½ 591 (600-1½)	600-2 591 (600-2)	900-3 891 (900-3)

SE-3: 05 DEC 2019 to 02 JAN 2020

SE-3: 05 DEC 2019 to 02 JAN 2020



Airport ID: TJSJ
Apt Name: LUIS MUNOZ MARIN
INTL
City: SAN JUAN
State: PUERTO RICO
Proc ID: VOR OR TACAN RWY 26
Amdt: 20A
Scale: 1:100,000



9. CAT E
BUILDING (328)

6. CATA/B
CRANE (288)

5. FINAL
BUILDING (121)

8. CAT D
AAO (610)

7. CAT C
TREE (423)

Federal Aviation Administration Categorical Exclusion Declaration

Date: 08/13/19

IFP: Griffin, Edward (Edward.CTR.Griffin@faa.gov)

Airport Contact: -

Request ID: TJSJ_190801_46

Single or Multiple Procedure: Multiple

Procedure Name(s): ILS OR LOC RWY 8, ILS OR LOC RWY 10, VOR OR TACAN RWY 8, VOR OR TACAN RWY 10, VOR OR TACAN RWY 28, NDB RWY 8, JAAWS ONE DEP

Procedure Request Description:

DEDDY FIX MAKEUP IS WITH SJU AND BQN. BQN HAS BEEN DESTROYED BY A HURRICANE AND IS NOT FEASIBLE TO REPAIR. REMOVE BQN FROM THE FIX MAKEUP AND CHANGE THE FIX TYPE TO WP AND DME ONLY FOR ALL PROCEDURES.

Declaration of Exclusion:

The FAA has reviewed the above referenced proposed action and it has been determined, by the undersigned, to be categorically excluded from further environmental documentation according to FAA Order 1050.1, "Environmental Impacts: Policies and Procedures." The implementation of this action will not result in any extraordinary circumstances in accordance with FAA Order 1050.1.

Basis for this Determination:

This review was conducted in accordance with policies and procedures in Department of Transportation Order 5610.1, "Procedures for Considering Environmental Impacts" and FAA Order 1050.1.

The applicable Categorical Exclusion is:

5-6.5.k: Publication of existing air traffic control procedures that do not essentially change existing tracks, create new tracks, change altitude, or change concentration of aircraft on these tracks. (ATO, AVS)

The above flight procedure has been developed within the accepted parameters.

Concurrence/Reviewed By:

Veronda Johnson

Date: August 13, 2019

Title: Environmental Protection Specialist

Approved By:

Debra L Hogan

Date: August 13, 2019

Title: Manager, Environmental, CI & NAS Analytics