

Flight Procedures Cover Page	Task Action: Abbreviated Amendment	Task Type: IAP	Estimated Chart Date: 07/09/2026	APWS Task ID: EC260E4AF3D2478E92B88447D2FEB5C8	APWS Project ID: DA3FB5EAE6B74827AF99A02649F4317D
Procedure: RNAV (GPS) RWY 6 AMDT 1A		Enroute: NO	Specialist: Bruce, Richard		Agreement Number:
Airport ID: 0A9			Airport City: ELIZABETHTON		State: TN
Facility ID:	Facility Type:	Flight Inspection Remark Type:			
Procedure Comments: PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021 GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION. HMV VORMON TRANSITION FROM VORTAC TO TACAN. KMZ FILES (2): 1. 0A9_RNAV_(GPS)_RWY_06_AMDT_1A_1 (FULL PROCEDURE). 2. 0A9_RNAV_(GPS)_RWY_06_AMDT_1A_2 (LNAV MISSED PENETRATIONS). ACTIVE DATA USED FOR 0A9 AIRPORT AND RUNWAYS. CONTACT RAKE MCGRAW, AJV-A422, (405) 954-8711.					

QUALITY
9
CHECKED
BEGUE

QUALITY
18
CHECKED


APP CRS	Rwy Ldg	4904
064°	TDZE	1575
	Apt Elev	1593

OLD


RNAV (GPS) RWY 6
ELIZABETHTON MUNI (ØA.9)

RNP APCH - GPS.	MISSED APPROACH: (Do not exceed 200K until CABYA) Climbing right turn to 5300 direct CABYA and hold.
⚠ -10°C	

AWOS-3PT 135.675	TRI CITY APP CON ★ 134.425 349.0	UNICOM 123.0 (CTAF) 0
---------------------	-------------------------------------	--------------------------



ELEV 1593	D	TDZE 1575
-----------	---	-----------



CATEGORY	A	B	C	D
LNAV MDA	3080-1¼ 1505 (1500-1¼)	3160-1½ 1585 (1600-1½)	3260-3 1685 (1700-3)	NA
CIRCLING	3080-1¼ 1487 (1500-1¼)	3160-1½ 1567 (1600-1½)	3260-3 1667 (1700-3)	NA