



Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: FIX	Estimated Chart Date: 10/02/2025	APWS Task ID: F03AF81D5D1C4EF2A324DE143E8BCCEE	APWS Project ID: B0523AE01D3A4D10825A1882AA7D02AF
Procedure: FIX GYPSM 0 CO US		Enroute: YES	Specialist: Campbell, Richard		Agreement Number:
Airport ID:			Airport City:		State:
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
<div>Procedure Comments: STANDALONE FIX PROJECT: FOLDER - CO_GYPSM_FIX_10-2-25.  GYPSM, CO - REV NO 0 (ESTABLISH).  REASON: ATC WILL USE IFP FIX GYPSM FOR AIRWAY CROSSING FIX, HOLDING AND ALTITUDE/ROUTING FOR KAPA AND KBJC ARRIVALS INTO D01.  ACTIVE AIRNAV-LAR VOR/DME (11/3/22), CYS VORTAC (8/17/17) AND GLL VOR/DME (2/4/16) (FIX MAKEUP).  CONTACT: ALLAN WILL (AJV-A423) - (405) 954-6103.</div> <div>QUALITY 18 CHECKED</div>					



**AMDT: NEW ENROUTE FIX SCALE: 1:500K HOLDING**











GVPSM (UD)

MIN 13000  
MAX 17000

270.0° (10E)  
35.93 NM

202.98° (13E)  
42.49 NM