


Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 07/09/2026	APWS Task ID: F8F44F0492A145519E78F0CA094027CE	APWS Project ID: 75E2A7B759FB4BD6BA059A6C09ACDEED
Procedure: RNAV (GPS) RWY 34 AMDT 2A		Enroute: NO	Specialist: Johnson, Raymond		Agreement Number:
Airport ID: KOQU			Airport City: NORTH KINGSTOWN		State: RI
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: PENDING AIRNAV DATA USED ADDED PVD AS BACK-UP ALTIMETER AND PUBLISH CONTINGENCY NOTES CANCELS NOTAM FDC 6/6184. CONTACT: RAKE MCGRAW, AJV-A422 MANAGER, 405.954.8711 QUALITY 29 CHECKED QUALITY 40 CHECKED					

RNAV (GPS) RWY 34
QUONSET STATE (OQU)


T
A Circling Rwy 5 NA at night.

MISSED APPROACH: Climb to 2500 direct SALME and on track 340° to FOSTY and hold.

UNICOM
122.95

Procedure NA for arrivals at FALMA on V374 eastbound and on V405 and T255 southeast bound.

ELEV	18	D	TDZE	12
------	----	----------	------	----



HIRL Rwy 16-34 **L**
MIRL Rwy 5-23 **L**
REIL Rwy 5 and 23 **L**

