

Flight Procedures Cover Page	Task Action: P-NOTAM	Task Type: IAP	Estimated Chart Date: 09/03/2026	APWS Task ID: FA3C0ADFA7FB49578A43801A706B8FE8	APWS Project ID: 4F0EA469AF66424B897E7C6648E9DCE6
Procedure: ILS or LOC RWY 35 AMDT 19E		Enroute: NO	Specialist: Johnson, Timothy		Agreement Number:
Airport ID: KSLN			Airport City: SALINA		State: KS
Facility ID: SLN	Facility Type: ILS	Flight Inspection Remark Type:			

Procedure Comments:

Visibility Initiative (Garmin) - Update IAP visibility minimums IAW Order 8260.3, Chapter 3, Section 3-3. Visibility Minimums.

PROCESSED IAW TECHNICAL SUPPORT GROUP (AJF-17) MEMO DATED 07/07/2021, SUBJECT: GUIDANCE FOR PROCEDURAL CHANGES REQUIRING FLIGHT INSPECTION/VALIDATION.

CONTACT: CASEY HILL (405) 954-0624.



