

Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 03/19/2026	APWS Task ID: FA7895FE378E458DAD15C9F298930960	APWS Project ID: C9F2E25EDB2A413C942CB965267D2BE9
Procedure: RNAV (GPS) RWY 17 AMDT 1		Enroute: NO	Specialist: Taylor, Jantzen		Agreement Number:
Airport ID: 60F			Airport City: SEYMOUR		State: TX
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			

Procedure Comments:
 CLEARS NOTAM !FDC 4/2208
 ACTIVE DATA USED FOR AIRPORT AND RUNWAY.
 CONTACT RAKE MCGRAW: (AJV-A422) 405.954.8711.

QUALITY
35
CHECKED

QUALITY
38
CHECKED

APP CRS 173°	Rwy Idg 4300
	TDZE 1344
	Apt Elev 1344

OLD


RNAV (GPS) RWY 17
SEYMOUR MUNI (60F)

RNP APCH - GPS.

▼ Obtain local altimeter on CTAF; when not received, use Sheppard AFB/Wichita Falls Muni altimeter setting and increase all MDAs 160 feet, increase LNAV Cat C and Circling Cat C visibility 1/2 SM. Procedure NA at night. Rwy 17 helicopter visibility reduction below 1 SM NA.



▲ NA MISSED APPROACH: Climb to 3000 direct ELLEN and hold.

FORT WORTH CENTER **133.5 350.35** CTAF **122.9**



SC-2, 02 OCT 2025 to 30 OCT 2025

SC-2, 02 OCT 2025 to 30 OCT 2025



CATEGORY	A	B	C	D
LNAV MDA	1700-1	356 (400-1)		NA
CIRCLING	1780-1 436 (500-1)	1800-1 456 (500-1)	2020-2 676 (700-2)	NA