





Flight Procedures Cover Page	Task Action: FLIGHT CHECK	Task Type: IAP	Estimated Chart Date: 04/17/2025	APWS Task ID: FE2FF780314445EA8FB58210F5B7809F	APWS Project ID: D732DB3B6AC8499DAFBFAF61728E19FA
Procedure: RNAV (GPS) RWY 17 ORIG		Enroute: NO	Specialist: Keefer, John		Agreement Number:
Airport ID: 1D8			Airport City: REDFIELD		State: SD
Facility ID:	Facility Type:	Flight Inspection Remark Type: New FC Slot			
Procedure Comments: Congressional inquiry 12/22/2023 Contact Joseph Zeder 405-954-9111. PENDING DATA USED DOCKET# 23-AGL-32 QUALITY 9 CHECKED BEGUE QUALITY 13 CHECKED					











**TAA Right Base 346 CW 076
TOWER (2274)
46-000281**

**TAA Right Base 346 CW 076
Stepdown TERRAIN+AAO (2189)**

**ID8
REDFIELD MUNICIPAL AIRPORT
REDFIELD, SOUTH DAKOTA
RNAV (GPS) RWY 17 ORIG
TAA RIGHT BASE
1:500K**





**TAA Left Base 257 CW 346
WINDMILL (2385)
46-041570**

**ID8
REDFIELD MUNICIPAL AIRPORT
REDFIELD, SOUTH DAKOTA
RNAV (GPS) RWY 17 ORIG
TAA LEFT BASE
1:500K**