800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

16

**Transmittal Letter 16-07** 

February 12, 2016

Orig

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows: .....EFFECTIVE UPON PUBLICATION AIRAC **FDC** FDC **STATE** CITY **AIRPORT** SUBJECT DATE **NUMBER** DATE 31-Mar-RNAV (GPS) RWY 27, 6/3254 02/08/16 ALWetumpka Wetumpka Muni

## **EFFECTIVE 31 MARCH 2016**

FDC 6/3254 08A IAP WETUMPKA MUNI, WETUMPKA, AL. RNAV (GPS) RWY 27, ORIG... CHART NOTE: PROCEDURE NA AT NIGHT. CHANGE HELICOPTER VISIBILITY REDUCTION NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 27, ORIG-A. 1601131554-PERM