

**Federal Aviation
Administration**

Transmittal Letter 16-09

March 11, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Apr-16	SD	Britton	Britton Muni	6/5955	02/23/16	RNAV (GPS) RWY 13, Amdt 1A

AIRAC Date: 28 APRIL 2016

FDC 6/5955 BTN IAP BRITTON MUNI, BRITTON, SD. RNAV (GPS) RWY 13, AMDT 1A... DELETE NOTE: PROCEDURE NA AT NIGHT. LNAV MDA 1820/HAT 504 ALL CATS. CHART NOTE: CIRCLING NA TO RWYS 1 AND 19. CHANGE HELICOPTER NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 13, AMDT 1B. 1602181714-PERM