

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Sep-15	AR	Lake Village	Lake Village Muni	5/1685	08/03/15	VOR-A, Amdt 8A

FDC 5/1685 M32 IAP LAKE VILLAGE MUNI, LAKE VILLAGE, AR. VOR-A, AMDT 8A... DELETE NOTE: CIRCLING TO RWY 1 NA AT NIGHT. CHART NOTE: PROCEDURE NA AT NIGHT.

THIS IS VOR-A, AMDT 8B. 1507281549-PERM