

U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION
TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated.
Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
ALLENDALE, SC	ALLENDALE COUNTY	17 OCTOBER 2013	1

TAKEOFF MINIMUMS:

RWY 17, 35 STANDARD

TEXTUAL DEPARTURE PROCEDURES:

TAKEOFF OBSTACLE NOTES:

NOTE: RWY 17, TREES BEGINNING 11' FROM DER, 366' RIGHT OF CENTERLINE, UP TO 100' AGL/222' MSL. VEHICLES ON ROADWAY BEGINNING 293' FROM DER, 558' LEFT OF CENTERLINE, UP TO 15' AGL/164' MSL. TREES 342' FROM DER, 577' LEFT OF CENTERLINE, UP TO 100' AGL/214' MSL. TREES BEGINNING 1962' FROM DER, 603' LEFT OF CENTERLINE, UP TO 100' AGL/246' MSL.

NOTE: RWY 35, TREES BEGINNING 38' FROM DER, 306' RIGHT OF CENTERLINE, UP TO 100' AGL/269' MSL. TREES BEGINNING 95' FROM DER, 324' LEFT OF CENTERLINE, UP TO 100' AGL/289' MSL.

CONTROLLING OBSTACLES:

QUALITY
CHECKED

U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION
TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated.
Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
ALLENDALE, SC	ALLENDALE COUNTY	17 OCTOBER 2013	1

REMARKS:

FLIGHT INSPECTED BY:

Robert Cooper

6/4/13

REQUIRED EFFECTIVE DATE:

ROUTINE

DEVELOPED BY:

GEORGETTE P. BARNETT

AJV-352

4/3/2013

APPROVED BY:

SUSAN CRUMB

AJV-352

JUL 31 2013

COORDINATED WITH:

ALPA, AOPA, NBAA, ZJX, AIRPORT MGR

CHANGES:

1. UPDATED TAKEOFF OBSTACLE NOTES FOR RWY 17/35.
2. AIRPORT ID CHANGED FROM K88J TO KAQX.

REASONS:

1. NEW THIRD PARTY SURVEY DATA
2. PER FPT REQUEST.

QUALITY
CHECKED