

U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION  
**TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)**

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated.  
Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
ALVA, OK	ALVA RGNL	20 AUGUST 2015	2

**TAKEOFF MINIMUMS:**

RWY 18, 36: STANDARD.

**TEXTUAL DEPARTURE PROCEDURES:**

**VISUAL CLIMB OVER AIRPORT:**

**TAKEOFF OBSTACLE NOTES:**

**NOTE: RWY 18:** SIGN 24 FEET FROM DER, 252 FEET LEFT OF CENTERLINE, 3 FEET AGL/1471 FEET MSL.

**NOTE: RWY 36:** BLDG 2523 FEET FROM DER, 327 FEET LEFT OF CENTERLINE, 74 FEET AGL/1549 FEET MSL.

**CONTROLLING OBSTACLES:**



U.S. DEPARTMENT OF TRANSPORTATION – FEDERAL AVIATION ADMINISTRATION  
**TAKEOFF MINIMUMS AND OBSTACLE DEPARTURE PROCEDURES (ODP)**

Bearings, headings, courses, tracks and radials are magnetic. Elevation and altitudes are in feet MSL. Altitudes are minimum altitudes unless otherwise indicated.  
Ceilings are in feet above airport elevation. Distances are in nautical miles. Visibilities are in statute miles or feet RVR unless otherwise indicated.

City, State	Airport	Effective Date	Amdt. No.
ALVA, OK	ALVA RGNL	20 AUGUST 2015	2

**REMARKS:**

**FLIGHT INSPECTED BY:** *Digitally signed by*  
JASON ERICKSON *JACOB POWERS*  
Jun 24, 2015

6/15/2015

**REQUIRED EFFECTIVE DATE:**

ROUTINE

**DEVELOPED BY:** *Digitally signed by*  
PABLO ORTIZ *JACOB POWERS*  
Jun 24, 2015

AJV-353

04/02/2015

**APPROVED BY:** *Digitally signed by*  
GEORGE GONZALEZ *JACOB POWERS* AJV-353  
Jun 24, 2015

**COORDINATED WITH:**

ZKC, END APP CON, ALPA, AOPA, NBAA, AMGR, ST. AV. DIR.

**CHANGES:**

1. REMOVED ALL REFERENCE RWY 8/26 AND RWY 17/35.
2. REMOVED RWY 8/35 DEPARTURE PROCEDURE AND DEPARTURE OBSTACLE.
3. ADDED TAKEOFF MINIMUMS (STANDARD) AND OBSTACLE NOTES RWY 18/36.

**REASONS:**

1. RWY NO LONGER EXIST.
2. NO LONGER REQUIRED.
3. NEW RWY 18/36; CURRENT LOW CLOSE-IN OBSTACLES FOR THE RWY 18/36.

