

**Federal Aviation
Administration**

Transmittal Letter 06-06

February 10, 2006

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
17-Feb-06	RQ	Aquadilla	Rafael Hernandez	6/1574	02/02/06	VOR RWY 8, Amdt 6

AIRAC Date: 17 FEBRUARY 2006

**FDC 6/1574 BQN FltP RAFAEL HERNANDEZ, AGUADILLA, PR.VOR RWY 8 AMDT
6 ... CHART: ALTERNATE MINIMUMS STANDARD.**

THIS IS VOR RWY 8, AMDT 6A.