800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 16-07

February 12, 2016

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION AIRAC **FDC** FDC STATE CITY **AIRPORT** SUBJECT DATE **NUMBER** DATE 31-Mar-CA 5/1879 02/08/16 Oceanside Oceanside Muni GPS RWY 24, Orig-B 16

EFFECTIVE 31 MARCH 2016

FDC **5/1879** OKB IAP OCEANSIDE MUNI, OCEANSIDE, CA. GPS RWY 24, ORIG-B... DELETE NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. DELETE NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: NIGHT LANDING: RWY 06 NA. CHANGE AIRPORT NAME TO READ BOB MAXWELL MEMORIAL AIRFIELD. THIS IS GPS RWY 24, ORIG-C. 1512302133-PERM