

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
25-Jun-15	GA	Nahunta	Brantley County	5/3473	04/30/15	RNAV (GPS) Z RWY 1, Orig

EFFECTIVE 25-JUN-2015

FDC **5/3473** 4J1 IAP BRANTLEY COUNTY, NAHUNTA, GA. RNAV (GPS) Z RWY 1, ORIG... CHART NOTE: NIGHT LANDING: RWY 19 NA. CHANGE HELICOPTER VISIBILITY NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. CHANGE PLANVIEW PROCEDURE NA NOTE FOR ARRIVALS AT SSI TO READ: PROCEDURE NA FOR ARRIVALS ON SSI VORTAC AIRWAY RADIALS 188 CW 326 AND ON T204 NORTHEAST BOUND. CHANGE PLANVIEW PROCEDURE NA NOTE FOR ARRIVALS AT AYS TO READ: PROCEDURE NA FOR ARRIVALS ON AYS VORTAC AIRWAY RADIALS 136 CW 180 AND ON T207 NORTHEAST BOUND. THIS IS RNAV (GPS) Z RWY 1 ORIG-A. 1504281840-PERM