800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 15-14

May 22, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION AIRAC **FDC** FDC STATE **CITY AIRPORT** SUBJECT DATE **NUMBER** DATE RNAV (GPS) RWY 17, 25-Jun-15 IΑ 5/9554 05/13/15 Chariton Chariton Muni Amdt 1A

EFFECTIVE 25 JUNE 2015

FDC 5/9554 CNC IAP CHARITON MUNI, CHARITON, IA. RNAV (GPS) RWY 17, AMDT 1A... CHART NOTE: PROCEDURE NA AT NIGHT. CHANGE HELICOPTER NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. DELETE NOTE: WHEN VGSI INOP, CIRCLING RWY 10 AND RWY 28 NA AT NIGHT. DELETE NOTE: STRAIGHT-IN/CIRCLING RWY 17 PROCEDURE NA AT NIGHT. DELETE NOTE: CIRCLING TO RWY 35 NA AT NIGHT. THIS IS RNAV (GPS) RWY 17, AMDT 1B. 1505111353-PERM