

**Federal Aviation
Administration**

Transmittal Letter 15-21

August 28, 2015

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
15-Oct-15	LA	Vivian	Vivian	5/8312	08/10/15	NDB RWY 9, Amdt 2A

AIRAC Date: 15 October 2015

FDC **5/8312** 3F4 IAP VIVIAN, VIVIAN, LA. NDB RWY 9, AMDT 2A... CHART NOTE:
PROCEDURE NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION
BELOW 1 SM NOT AUTHORIZED. THIS IS NDB RWY 9, AMDT 2B. 1506142211-
PERM