800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

31-Mar-16

Transmittal Letter 16-08

February 26, 2016

Orig

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION AIRAC FDC FDC **STATE CITY AIRPORT SUBJECT** DATE **NUMBER** DATE RNAV (GPS) RWY 13, 6/3507 02/16/16

EFFECTIVE 31 MARCH 2016

NE

Imperial

FDC 6/3507 IML IAP IMPERIAL MUNI, IMPERIAL, NE. RNAV (GPS) RWY 13, ORIG... CHART NOTE: CIRCLING NA TO RWYS 3 AND 21. CHANGE HELICOPTER VISIBILITY REDUCTION NOTE TO READ: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 13 ORIG-A. 1602112144-PERM

Imperial Muni