

**Federal Aviation
Administration**

Transmittal Letter 16-14

May 20, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
23-Jun-16	WV	Huntington	Tri-State/Milton J Ferguson Field	5/6941	5/5/16	RADAR 1, Amdt 8

AIRAC Date: 23 JUNE 2016

FDC 5/6941 HTS IAP TRI-STATE/MILTON J FERGUSON FIELD, HUNTINGTON, WV. RADAR 1, AMDT 8... ASR 12 MDA 1280/HAT 452 ALL CATS. FAS OBST: 1052 TOWER 382413N/0823629W. TDZE: RWY 12/30:828. CHANGE HELICOPTER NOTE TO READ: RWY 12 HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS RADAR 1, AMDT 8A. 1511202143-PERM