

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 16-08

February 26, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
31-Mar-16	CO	La Junta	La Junta Muni	5/1868	02/16/16	Takeoff Minimums and (Obstacle) DP, Amdt 3

EFFECTIVE 31 MARCH 2016

FDC 5/1868 LHX ODP LA JUNTA MUNI, LA JUNTA, CO. TAKEOFF MINIMUMS
AND (OBSTACLE) DEPARTURE PROCEDURES AMDT 3... NOTE: RWY 26,
ROD 196 FT FROM DER, 445 FT LEFT OF CENTERLINE, 10 FT AGL/4241 FT
MSL. FENCE 224 FT FROM DER, 198 FT RIGHT OF CENTERLINE, 7 FT
AGL/4235 FT MSL. ALL OTHER DATA REMAINS AS PUBLISHED. THIS IS
TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES, AMDT
3A. 1512041434-PERM