

**Federal Aviation
Administration**

Transmittal Letter 16-21

August 26, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:EFFECTIVE UPON PUBLICATION						
AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
13-Oct-16	ND	Rugby	Rugby Muni	6/2712	8/15/16	RNAV (GPS) RWY 30, Orig-A

AIRAC Date: 15 SEPTEMBER 2016

FDC 6/2712 RUG IAP RUGBY MUNI, RUGBY, ND. RNAV (GPS) RWY 30, ORIG-A... CHART NOTE: RWY 30 HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. DELETE NOTE: NIGHT LANDING: RWY 30 NA FOR CAT C AIRCRAFT. DELETE DESCENT ANGLE 3.00/TCH 45. DELETE PROFILE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT. CHART PROFILE NOTE: VISUAL SEGMENT-OBSTACLE. THIS IS RNAV (GPS) RWY 30, ORIG-B. 1606161721-PERM