

U.S. Department
of Transportation

800 Independence Ave., S.W.
Washington, D.C. 20591

**Federal Aviation
Administration**

Transmittal Letter 17-13

May 5, 2017

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
22-Jun- 17	NC	Rutherfordton	Rutherford Co - Marchman Field	7/4926	4/13/17	LOC RWY 1, Amdt 3

AIRAC Date: 22 JUNE 2017

FDC 7/4926 FQD IAP RUTHERFORD CO - MARCHMAN FIELD,
RUTHERFORDTON, NC. LOC RWY 1, AMDT 3... S-1 HAT 541 ALL CATS.
DASCA FIX MINIMUMS (DUAL VOR RECEIVERS OR DME REQUIRED): S-1
HAT 381 ALL CATS. CHART TDZE 1059, DELETE THRE 1057. DELETE NOTE:
VGSI AND DESCENT ANGLES NOT COINCIDENT. THIS IS LOC RWY 1, AMDT
3A. 1702152029-PERM