PREPARED BY THE PRODUCT SUPPORT GROUP, AJV-34

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

| AIRAC DATE | STATE | CITY | AIRPORT | FDC NUMBER | FDC DATE | SUBJECT |
|---------------|-------|--------|-------------|---------------|----------|---------------------------------|
| 2-May-13 | AZ | Tucson | Tucson Intl | 3/7886 | 777712 | RNAV (RNP) Y RWY 29R, Orig-B |

FDC 3/7886 TUS FI/P IAP TUCSON INTL, TUCSON, AZ. RNAV (RNP) Y RWY 29R, ORIG-B... CHART PLANVIEW NOTE: RADAR REQUIRED FOR PROCEDURE ENTRY AT JOKIM (IAF). DELETE PLANVIEW NOTE: PROCEDURE NA FOR ARRIVALS AT JOKIM ON T306 EASTBOUND. THIS IS RNAV (RNP) Y RWY 29R, ORIG-C.