

**Federal Aviation
Administration**

Transmittal Letter 16-11

April 8, 2016

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

26-May-2016	VT	West Dover	Deerfield Valley Rgnl	6/2148	04/01/16	RNAV (GPS) RWY 1, Orig
-------------	----	------------	-----------------------	--------	----------	---------------------------

AIRAC Date: 26 MAY 2016

FDC 6/2148 4V8 IAP DEERFIELD VALLEY RGNL, WEST DOVER, VT. RNAV (GPS)
RWY 1, ORIG... CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE:
HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. 34:1 IS NOT
CLEAR. DELETE NOTE: CIRCLING TO RWY 19 NA AT NIGHT. DELETE NOTE:
PROCEDURE NA 0200 LOCAL TO DAWN. THIS IS RNAV (GPS) RWY 1, ORIG-A.
1603041955-PERM.