

**Federal Aviation
Administration**

Transmittal Letter 18-23

September 21, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
8-Nov-18	NY	Glens Falls	Floyd Bennett Memorial	8/1703	9/13/18	RNAV (GPS) RWY 19, Amdt 1B

AIRAC Date: 8 NOVEMBER 2018

FDC **8/1703** GFL IAP FLOYD BENNETT MEMORIAL, Glens Falls, NY. RNAV (GPS) RWY 19, AMDT 1B... DELETE NOTE: RWY 12, 30 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NA. DELETE NOTE: DME/DME RNP-0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. DELETE: DESCENT ANGLE 3.44/TCH 50. DELETE NOTE: VGSI AND DESCENT ANGLES NOT COINCIDENT AND (VGSI ANGLE 3.00/TCH 50). CHART PROFILE NOTE: VISUAL SEGMENT - OBSTACLES. THIS IS RNAV (GPS) RWY 19, AMDT 1C. 1808062012-PERM