

**Federal Aviation
Administration**

Transmittal Letter 18-19

July 27, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
13-Sep-18	MO	Salem	Salem Memorial	8/1892	7/25/18	RNAV (GPS) RWY 17, Orig

AIRAC Date: 13 SEPTEMBER 2018

FDC **8/1892** K33 IAP SALEM MEMORIAL, Salem, MO. RNAV (GPS) RWY 17, ORIG...
PBN REQUIREMENTS NOTE: RNP APCH. DELETE NOTE: DME/DME/RNP 0.3 NA.
DELETE NOTE: GPS OR RNP-0.3 REQUIRED. CHART NOTE: RWY 17
HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. THIS IS
RNAV (GPS) RWY 17, ORIG-A. 1807231736-PERM