

**Federal Aviation
Administration**

Transmittal Letter 18-25

October 19, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

6-Dec-18	OR	Portland	Portland Intl	8/0582	10/3/18	ILS OR LOC RWY 28L, Amdt 5
----------	----	----------	---------------	--------	---------	-------------------------------

AIRAC Date: 6 DECEMBER 2018

FDC **8/0582** PDX IAP PORTLAND INTL, Portland, OR. ILS OR LOC RWY 28L, AMDT
5... DELETE NOTE: AUTOPILOT COUPLED APPROACH NA BELOW 580. CHART
NOTE: AUTOPILOT COUPLED APPROACH NA BELOW 880. THIS IS ILS OR LOC
RWY 28L, AMDT 5A. 1808301300-PERM