

**Federal Aviation
Administration**

Transmittal Letter 18-19

July 27, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBE	FDC DATE	SUBJECT
13-Sep-18	IA	Mapleton	James G Whiting Memorial Field	8/5671	7/23/18	RNAV (GPS) RWY 2, Orig

AIRAC Date: 13 SEPTEMBER 2018

FDC **8/5671** MEY IAP JAMES G WHITING MEMORIAL FIELD, Mapleton, IA. RNAV (GPS) RWY 2, ORIG... CHART NOTE: PROCEDURE NA AT NIGHT. DELETE NOTE: DME/DME RNP - 0.3 NA. PBN REQUIREMENTS NOTE: RNP APCH. 20:1 IS NOT CLEAR. 34:1 IS NOT CLEAR. CHART NOTE: RWY 2 HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. THIS IS RNAV (GPS) RWY 2, ORIG-A. 1807161758-PERM