

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 19-01**

**November 16, 2018**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-54  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME,  
LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY  | AIRPORT     | FDC<br>NUMBER | FDC<br>DATE | SUBJECT            |
|---------------|-------|-------|-------------|---------------|-------------|--------------------|
| 3-Jan-19      | ND    | Fargo | Hector Intl | 8/6519        | 11/1/18     | VOR RWY 36, Orig-D |

**AIRAC Date: 3 JANUARY 2019**

**FDC 8/6519 FAR IAP HECTOR INTL, Fargo, ND. VOR RWY 36, ORIG-D...  
CHART CIRCLING ICON. THIS IS VOR RWY 36, ORIG-E. 1809101630-PERM**