Federal Aviation Administration

**Transmittal Letter 15-21** 

August 28, 2015

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DAT	SUBJECT
15-Oct-15	IL	Dixon	Dixon Muni-Charles R Walgreen Field	5/5033	08/06/15	RNAV (GPS) RWY 26, Orig-A

## AIRAC Date: 15 October 2015

FDC **5/5033** C73 IAP DIXON MUNI-CHARLES R WALGREEN FIELD, DIXON, IL. RNAV (GPS) RWY 26, ORIG-A... CHANGE HELICOPTER VISIBILITY NOTE TO: HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED. CHANGE ALTIMETER SETTING NOTE TO READ: WHEN LOCAL ALTIMETER SETTING NOT RECEIVED, USE ROCHELLE ALTIMETER SETTING. CHART NOTE: NIGHT LANDING: RWY 08, 26 NA. THIS IS RNAV (GPS) RWY 26 ORIG-B. 1508031432-PERM