

**Federal Aviation
Administration**

Transmittal Letter 19-05

January 11, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
28-Feb-19	NY	Weedsport	Whitfords	8/2807	1/8/19	Takeoff Minimums and Obstacle DP, Orig

AIRAC Date: 28 FEBRUARY 2019

FDC **8/2807** B16 ODP WHITFORDS, Weedsport, NY. TAKEOFF MINIMUMS AND
(OBSTACLE) DEPARTURE PROCEDURES ORIG... TAKEOFF MINIMUMS: DELETE
ALL REFERENCES TO RWYS 1, 19. ALL OTHER DATA REMAINS AS PUBLISHED.
THIS IS TAKEOFF MINIMUMS AND (OBSTACLE) DEPARTURE PROCEDURES,
ORIG-A. 1810261309-PERM