

**Federal Aviation
Administration**

Transmittal Letter 18-13

May 4, 2018

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

21-Jun-18	MI	Linden	Prices	8/8227	4/23/18	RNAV (GPS) RWY 27, Amdt 1
-----------	----	--------	--------	--------	---------	------------------------------

AIRAC Date: 21 JUNE 2018

FDC 8/8227 9G2 IAP PRICES, Linden, MI. RNAV (GPS) RWY 27, AMDT 1...
CHART NOTE: PROCEDURE NA AT NIGHT. CHART NOTE: RWY 27
HELICOPTER VISIBILITY REDUCTION BELOW 1 SM NOT AUTHORIZED.
DELETE NOTE: "DME/DME RNP-0.3 NA. PBN REQUIREMENT NOTE: RNP
APCH. TDZE 919. LNAV MDA 1400/HAT 481 ALL CATS. THIS IS RNAV (GPS)
RWY 27, AMDT 1A. 1804121216-PERM