Federal Aviation Administration

**Transmittal Letter 19-23** 

**September 20, 2019** 

## PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY       | AIRPORT                               | FDC<br>NUMBER | FDC<br>DATE | SUBJECT                      |
|---------------|-------|------------|---------------------------------------|---------------|-------------|------------------------------|
| 11/7/2019     | NE    | Hartington | Hartington<br>Muni/ Bud<br>Becker Fld | 9/5680        | 9/17/2019   | RNAV (GPS) RWY 31,<br>Orig-C |

## **AIRAC Date: 7 NOVEMBER 2019**

FDC 9/5680 0B4 IAP HARTINGTON MUNI/ BUD BECKER FLD, Hartington, NE. RNAV (GPS) RWY 31, ORIG-C... DELETE CIRCLING MINIMUMS. DELETE NOTE: CIRCLING NA TO RWY 3 AND 21. THIS IS RNAV (GPS) RWY 31, ORIG-D. 1909091535-PERM