

**Federal Aviation
Administration**

Transmittal Letter 19-24

October 4, 2019

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
11/7/2019	SD	Aberdeen	Aberdeen Rgnl	9/5681	9/18/2019	ILS OR LOC RWY 31, Amdt 13A

AIRAC Date: 7 NOVEMBER 2019

FDC 9/5681 ABR IAP ABERDEEN RGNL, Aberdeen, SD. ILS OR LOC RWY 31,
AMDT 13A... DELETE CIRCLING MINIMUMS. THIS IS ILS OR LOC RWY 31, AMDT
13B. 1909091535-PERM