800 Independence Ave., S.W. Washington, D.C. 20591

Federal Aviation Administration

Transmittal Letter 15-14

May 22, 2015

PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53 (AVAILABLE ON THE WEB AT HTTP://NFDC.FAA.GOV)

The enclosed Standard Instrument Approach Procedures, Departure Procedures/Takeoff Minimums and Fix Actions are effective as indicated.

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:

......EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
25-Jun-15	UT	Delta	Delta Muni	5/6852	05/08/15	RNAV (GPS) RWY 17, Amdt 1B

EFFECTIVE 25-JUN-2015

FDC **5/6852** DTA IAP DELTA MUNI, DELTA, UT. RNAV (GPS) RWY 17, AMDT 1B... DELETE NOTE: CIRCLING TO RWY 30 NA AT NIGHT. CHART NOTE: HELICOPTER VISIBILITY REDUCTION BELOW 3/4 SM NOT AUTHORIZED. 34:1 IS NOT CLEAR. THIS IS RNAV (GPS) RWY 17, AMDT 1C. 1505051917-PERM