

**Federal Aviation  
Administration**

**Transmittal Letter 23-09**

**March 3, 2023**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC, LOC/DME, LDA,  
LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS, MLS/DME,  
MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs, Identified as follows:  
.....EFFECTIVE UPON PUBLICATION

AIRAC DATE	STATE	CITY	AIRPORT	FDC NUMBER	FDC DATE	SUBJECT
4/20/2023	OK	Enid	Enid Woodring Rgnl	3/3127	2/17/2023	ILS OR LOC RWY 35, Amdt 7B

**AIRAC Date: 20 APRIL 2023**

FDC 3/3127 WDG IAP ENID WOODRING RGNL, ENID, OK. ILS OR LOC RWY 35, AMDT 7B...  
DELETE R-025 FROM KINGFISHER TACAN TO IAF PODDS IN PLANVIEW. THIS IS ILS OR  
LOC RWY 35, AMDT 7C. 2301121936-PERM