

U.S. Department  
of Transportation

800 Independence Ave., S.W.  
Washington, D.C. 20591

**Federal Aviation  
Administration**

**Transmittal Letter 16-02**

**December 4, 2015**

**PREPARED BY THE AERONAUTICAL INFORMATION GROUP, AJV-53  
(AVAILABLE ON THE WEB AT [HTTP://NFDC.FAA.GOV](http://NFDC.FAA.GOV))**

**The enclosed Standard Instrument Approach Procedures, Departure  
Procedures/Takeoff Minimums and Fix Actions are effective as indicated.**

By amending: §97.23 VOR, VOR/DME, VOR or TACAN, and VOR/DME or TACAN; §97.25 LOC,  
LOC/DME, LDA, LDA/DME, SDF, SDF/DME; §97.27 NDB, NDB/DME; §97.29 ILS, ILS/DME, MLS,  
MLS/DME, MLS/RNAV; §97.31 RADAR SIAPs; §97.33 RNAV SIAPs; and §97.35 COPTER SIAPs,  
Identified as follows: .....EFFECTIVE UPON PUBLICATION

| AIRAC<br>DATE | STATE | CITY       | AIRPORT         | FDC<br>NUMBER | FDC<br>DATE | SUBJECT                     |
|---------------|-------|------------|-----------------|---------------|-------------|-----------------------------|
| 7-Jan-16      | TN    | Smithville | Smithville Muni | 5/2872        | 11/23/15    | RNAV (GPS) RWY 6,<br>Amdt 3 |

**AIRAC Date: 7 January 2016**

**FDC 5/2872** 0A3 IAP SMITHVILLE MUNI, SMITHVILLE, TN. RNAV (GPS) RWY  
6, AMDT 3... CHANGE THRE 1079 TO TDZE 1079.

**THIS IS RNAV (GPS) RWY 6, AMDT 3A. 1511131751-PERM**